











David Guyan

From: ogalsworthy@yahoo.co.uk
Sent: 09 February 2019 14:05
To: raynesbranch@mr-carpet.co.uk; anthonyrickard@mr-carpet.co.uk
Cc: matt_mowlam@yahoo.co.uk
Subject: Ref R17795 34 Algarve Road

 (140 KB)  (153 B)  (112 KB)  (125 B)  (97 KB)  (174 B)  (113 KB)

 (279 B)  (66 KB)  (911 B)

Dear Anthony,

Thank you very much for your time earlier, it is much appreciated.

Following on from our conversation earlier today, please see below a list of the concerns I have about the carpet and the photos to substantiate them:

1. The carpet on the first landing has not been laid in line with the line of the top step. Given that the loop carpet has a clear line, the ill fitting of the carpet is very obvious: