

# PRODUCT SPECIFICATION



910 WINDSOR



## GENERAL INFORMATION

<b>type:</b>	High low loop pile
<b>yarn content:</b>	50% Wool 50% PP
<b>gauge:</b>	5/32"
<b>tuft density (tufts /m<sup>2</sup>):</b>	113,400
<b>pile weight ex.cloth (gr./m<sup>2</sup>):</b>	840
<b>total weight(gr./m<sup>2</sup>):</b>	1800
<b>pile height:</b>	4 mm
<b>total height:</b>	6 mm
<b>width:</b>	4 & 5m
<b>backing:</b>	Action Back
<b>Scotchgard:</b>	Yes
<b>number of colours:</b>	5

## COLOURS:

nr	name	nr	name	nr	name
24	Bracken	32	Parchment	39	Pebble
42	Bamboo	89	Smoke		

## USER APPLICATIONS:

<b>rating:</b>	Heavy Domestic / Heavy Contract
<b>Gut reg. No:</b>	

## PRODUCT SYMBOLS:



### Installation

If you are ordering in quantity and require colour matching, please let us know when you are placing your order.  
For all contract locations, we recommend an all over stick down method (BS5325(1983))

### Maintenance

Correct and regular maintenance will increase carpet life and help keep its appearance for longer. Please note that light shades are inevitably more prone to soiling. We do not recommend these for use in heavy traffic areas.

We recommend regular vacuuming once a week for all our carpets in all areas - but this should be increased to at least twice a week in more heavily used areas. 'Shading' is the effect of unequal pressure on pile carpets and is a natural characteristic, not a manufacturing fault.

All pile fabrics will flatten in traffic lanes. This is a natural characteristic, not a manufacturing fault (regular vacuuming will reduce the effect).

We recommend the use of an upright vacuum cleaner with beater bar on all products.

### Important

Due to the limitations of dye technology colours may vary from those shown on the sampling. Colour matching also cannot be guaranteed between 4 metre and 5 metre widths, as they too will be from different production runs and the colours may vary slightly.

It is strongly recommended that a protection mat i.e. keyhole mat or similar is used under castor chairs.

No claims will be considered as a result of improper application, installation or maintenance.