


P29896
Dannehy
20FS

1st floor


P29896
Donnelly
3065




Ground floor

P29896
Dannelly

(4 of 5)





Concrete floor
 Allow 50% New steel (Some missing/Loose)
 UPD Not damaged 8/20 TWIST.