



needs cribfill in
sub floor joints

EM needs F/P finish
over existing ply

(10/1)

532122

MR. C HADFIELD
192 SHEEN ROAD
RICHMOND
TWIN FALL

Sheet: of: