



LANDING DETAIL



R15557  
RUBER  
51 EPSOM LANE SOUTH  
TADWORTH. KT20.

1 2.


FIRST FLOOR.



STAIRS 10 x 41 x 79  
1 x BRIDGE.


← DIRECTION OF RIB.

GROUND FLOOR.



REPAIR AROUND SLAB.

FLOORBOARDS NOT GOOD  
BLOCKS LOOSE ON  
GROUND FLOOR.  
CIMER AWARE.



R15557  
 RUBER  
 51 EPSOM LANE SOUTH  
 TADWORTH.

2 3

$$585 \times 500$$


$$670 \times 4$$

$$475 \times 4$$

---


$$17.30 \times 5.00 =$$

$$86.50m^2$$



R15557  
 RUBER  
 SI EPSOM LANE 9TH  
 TADWORTH.

3 3,