

F23667 De Wit

Flat 2, 9 Greyhound Road W6 9NH


Thursday, 17 November 2016

Prepared For Manx Carpets

Identified 6 Issues

Colin Symonds

Mr Carpet Ltd



Hallway

Excessive pilling



Hallway

Excessive pilling



Bedroom

Excessive pulling



Excessive Pulling

The front door is rubbing on the carpet at the entrance into the property so we would recommend to the customer that the door should be trimmed by the appropriate tradesman to help improve the pilling at this juncture, however the bedrooms are pilling badly too and there are no issues with doors rubbing in those areas.



Door Rubbing On Carpet

Front Door rubbing is also not helping the pilling situation



Hallway Pilling Outside Kitchen And Inside Front Door