



F26596

Colin Symonds

Mr Carpet Ltd

39 Culverden Road SW12 9LT

Tuesday, 28 August 2018

Prepared For Mrs Sam Bourne

4 Issues Identified



Issue

Top Riser

Assigned To

F26596

Comments

The existing carpet needs to be cut back and fitted under the lip of the nosing on the landing



Issue

Top Riser

Assigned To

F26596

Comments

The existing scotia beading will need to be removed by the appropriate tradesman and then gap filled with mastic or silicone to facilitate stair runner



Issue

Bottom Step / Bullnose

Assigned To

F26596

Comments

To obtain a more aesthetically pleasing finish the expansion gap in the wooden floor installed to the hallway at the bottom of the bullnose step will require filling and tidying up by the appropriate tradesman prior to carpet installation.



Issue

Alarm Cable

Assigned To

F26596

Comments

The alarm cable on the top Riser and top step cannot be installed under the new stair runner! This cable will therefore be visible on the right hand side or the new runner unless it can be removed or re-routed by the appropriate tradesman prior to installation.