

P27356 - Howard De Walden Estates

101-102 Marylebone High St. (Flat B)

Wednesday, 2 November 2016

Prepared For Howard De Walden Estates

Identified 5 Items

Nigel Symonds

Mr Carpet Ltd



Underlay

The underlay is in poor condition therefore we recommend replacing the underlay throughout this property



Bathroom Flooring

The existing plywood joints are showing through the existing vinyl & may show through the new vinyl if new plywood isn't laid?



Bathroom Flooring

The existing plywood joints are showing through the existing vinyl & may show through the new vinyl if new plywood isn't laid?



Bathroom Door

If new plywood is fitted the door will need to be trimmed. This work is not included in our quote



Bedroom 1 - Large Wardrobes

We have allowed to carpet under these large wardrobes, however although every care will be taken when moving them to install the carpets we cannot accept any responsibility if any
