

Colin Symonds  
Mr Carpet Ltd

# P27810 NICHOLS

---

29 Disraeli Road SW15 2DR

Tuesday, 25 July 2017

Prepared For James Nichols

4 Issues Identified



### **HOLES IN FLOOR BY DOOR TO ROOF TERRACE**

Repair required prior to carpet installation



### **BROKEN FLOORBOARD ON LANDING**

Floorboard needs repair or replacing prior to carpet installation



### **CHECK PAINT AT SIDES OF ALL STAIRS IS SUFFICIENT TO ACCOMMODATE PROPOSED STAIR RUNNER WIDTH**

Extend paint as required to each flight of Stairs



### **BROKEN FLOORBOARD**

Repair/ replace Floorboard prior to carpet installation