

S29901 Fitzgerald-O'Connor

Tuesday, 20 February 2018

4 Issues Identified



Issue 1

Needs restretch



Issue 2

Lump under carpet. Could be wire, could be underlay overlapping. Please inspect and restretch



Issue 3

Restretch in loft room



Issue 4

Restretch in loft room
