



Confidential Report

Our Ref: 25/07129C/03/16

**British Carpet Technical Centre
Wira House, West Park Ring Road,
Leeds, LS16 6QL**

Tel No: +44 (0)113 2591999



BCTC
CARPET TECHNICAL CENTRE

British Carpet Technical Centre
Wira House
West Park Ring Road
Leeds, LS16 6QL
England

Tel: +44 (0)113 259 1999
Web: <http://www.bttg.co.uk>
Email: CSLeeds@bttg.co.uk

15 March 2016

Our Ref: 25/07129C/03/16
Your Ref:

Page 1 of 2

Client: ITC Natural Luxury Flooring
Schering 45
8281 JW Genemuiden
The Netherlands

Job Title: **Body Voltage Test on One Sample of Carpet**

Clients Order Ref: --

Date of Receipt: 3 March 2016

Reference: **Chablis**
Description of Sample: Cut Pile
Secondary Backed
Tufted Carpet
Measurements: 145cm x 300cm

Work Requested: BCTC were requested to carry out a Body Voltage Test on the sample of carpet supplied.



15 March 2016

Page 2 of 2

Our Ref: 25/07129C/03/16
Your Ref:

ITC Natural Luxury Flooring

Assessment of Static Electrical Propensity – Walking Test (*)

One specimen from the sample was conditioned and tested in accordance with BS ISO 6356:2012 at 25± 3%rh and 23± 1°C.

One operator wearing BAM soled sandals made three walks, each of 100 paces, up and down the length of the sample whilst holding a probe connected to a Static Voltmeter. The mean of the five highest troughs attained during each walk was determined.

Mean Body Voltage (kV)

	-1.3
	-1.3
	<u>-1.3</u>
Mean:	-1.3


The sign - denotes a negative and + a positive charge on the body.

N.B:

In our opinion, based on the test carried out on the sample of carpet supplied; the result indicates the sample meets the maximum requirement allowed of ≤2.0kV, as stated in BS EN 1307:2014, British Standard Textile floor coverings – Classification of floor coverings.

*Non UKAS test

An estimation of uncertainty of measurement has not been taken into account when making a judgement to any pass/fail criteria.

Reported by:  K Pillinger, Laboratory Technician

Countersigned by:  P Doherty, Operational Head

Enquiries concerning this report should be addressed to Customer Services.