


F/F FRONT & S&L.

Job No: F29144
Name: HUMBLE
Address: 57 CHALTON RD
SW6 7NH
Tel:
Sheet: 1 OF 5




NAVAN NAV-906

RUNNER TO
1ST FIGHT
ONLY

READ INFO SHEET AND SPEAK
TO SHOP IF UNCLEAR BEFORE
STARTING FITTING

FIRST FLOOR

Job No: F29144
 Name: HUMBLE
 Address: 57 CHAMBERLAIN RD
 SW6 7NH
 Tel:
 Sheet: 2 of 5



G/F
 BN AS STAIR
 12 STEPS 74
 RISER 74x16

LIOR 0890



Job No: F291144


Name: HUMBLE

Address: 57 CANNON RD
SW6 7NH



Tel:

Sheet: 3 of 5



TOP FLOOR



Glass panel in bedroom / finish from landing to parquet:

	
<p>Carpet will be fitted up against the base of the glass panel, as per normal skirting board. At the top of the step (end of glass panel) the carpet will be turned to finish, and at the top of the step can be fitted to finish under the edge of the landing (leaving the riser of the top step visible)</p> <p>Jamie/Martin – Call and speak to John, Pete or Paul if this is unclear</p>	<p>Carpet will run over the step/edge to finish against the parquet floor</p> <p>Jamie/Martin – Call and speak to John, Pete or Paul if this is unclear</p>

Areas that need attention prior to fitter's arrival:

	
<p>First floor rear bedroom: The floorboard inside the door has some chunks missing and ideally would be replaced prior to the carpet fitting.</p> <p>Customer response: We will fill this gap ahead of the fitting</p>	<p>Top Floor bedroom: The gap under the cupboard in the bedroom may not be fully covered by the carpet/underlay and may appear to be a dark shadow along the cupboard.</p> <p>Customer response: The gap here is 15mm - will this not be covered by the carpet build up?</p> <p>Jamie/Martin: Fit with gripper but DO NOT bolster down and let run in a bit to reduce any possible gap visibility</p>



First Floor landing opposite the bathroom: There is a large gap that will not be fully covered by the carpet and will look like a dark shadow where higher than the carpet and underlay

Customer response: Customer will fill this gap ahead of the fitting



Edge of first floor landing/top of runner: The edge of the landing has a small quadrant that would not allow the runner on the riser to fix flat against the riser as you would like.

There are two options:

1: **Preferred:** You have the quadrant removed / step painted as required so that the riser is flat and runner can fit against it. This is so the runner starts under the edge of the landing as per our previous example picture.



or

2: Run the carpet full width over the step and have the runner start from the tread of the top step.

Customer response: Customer will remove the quadrant and paint prior to arrival