


Loft bed cupboard

R17298

Mrs H Seymour
47 Dora Road
Wimbledon
SW19 7EZ



This piece not
fitted when bedroom
done.

Carpet on site, needs
seaming on. Might
need to be in 2 pieces

Also: Customer has a problem with under floor
heating in loft dressing room. It happened
when we fitted the carpets.

Need to pull back the carpet + inspect

JC will meet you on site.

Ring JC when on way

(10/1)