


R17512

Malden Manor  
Bowling Club  
Mans Park  
New Malden  
ICTJ 6AU



EXISTING SUB  
FLOOR SCREEN IS  
CALCIUM SULPHATE  
ANHYDRATE

Needs P12 prime  
u Slap 1100

1 P4 Tackifier

Put back  
own tiles

This area, but customers own  
tiles + butt up to main tiles

Loc 1