

Fitting Instructions R19089 Kolacki

Alan – Thursday 26/09/23

(PLEASE READ BEFORE GOING TO SITE)

PLEASE BE VERY CAREFUL OF NEW PAINTWORK & NEW TIMBER FLOORING WHILST WORKING ON SITE

****PLEASE DON'T USE ANY PINS AS U/FLOOR HEATING LAID THROUGHOUT****

Remedial works required where existing carpets in the rooms meet tiles in the Ensuite bathrooms & timber floors in the basement hall & 1st floor landing :-

Basement TV Room to Basement hall

- Peel carpet back at junction with timber flooring in hall & glue a 6mm shim in place to raise the carpet height to match the new timber fitted in basement hall
- Stick gripper in front to existing 3mm wide Ali trim (Fitted by wood floor Co.) and patch in small amount of low tog U/Lay as required before stretching & fitting carpet up to the existing Ali trim

Basement Bedroom to bathroom ensuite

- Peel carpet back, remove existing Pewter tile lip & fit a Satin Nickel Tile lip instead
- Re-stretch & refit carpet up to tile lip (Existing shim to remain in situ at this doorway)

1st floor Guest Bedroom to 1st floor landing

- Peel carpet back at junction with timber flooring fitted on the landing, stick gripper in front to existing 3mm wide Ali trim (Fitted by wood floor Co.) and patch in small amount of low tog U/Lay as required before stretching & fitting carpet up to the existing Ali trim

1st floor Guest Bedroom to bathroom ensuite

- Peel carpet back, remove existing Pewter Tile lip & fit a Satin Nickel Tile lip instead
- Patch in small amount of low tog U/Lay & stick gripper before stretching & fitting the carpet up to tile lip (Existing shim to remain at this doorway)

1st floor Study to 1st floor landing

- Peel carpet back at junction with timber flooring fitted on the landing, stick gripper in front to existing 3mm wide Ali trim (Fitted by wood floor Co.) and patch in small amount of low tog U/Lay as required before stretching & fitting carpet up to the existing Ali trim

PLEASE DON'T USE ANY PINS AS U/FLOOR HEATING LAID THROUGHOUT

Charge customer cash direct for remedial work (Quoted approx £50 - £60)

(FYI - We're supplying all of the additional trims, shims & ancillaries free of charge due to the original error we made fitting the wrong colour bars)