


526902

Dixon



1) Not below Elite 405
Platinum 45

Bell Joint 25.22
Chalk -10%

wood
why
outside
mkr (43)

Also. ext stair ext canopy loose

5th stair up.

Fix to make safe

$$4.75 \times 5 = 23.75 \text{ m}^2$$