

AVAN !! ATTEND

mrcarpets


✓ • BOTTOM RUNNER STEP
KEEPS COMING AWAY,

RE-PIN

✓ • GRIPPER ON MAIN LAMP
NEEDS RE-TACKLING.


✓ • FINISH ON LANDING (1ST) RISER
IS NOT GREAT. LOOK @ NEATENING
IT.

Job No: (S) 28231
Name: SIDDIQ
Address: Avon Street 6+7
RD 9/6/2016
Tel:
Sheet: 1 of 1



UPWT NEW
2x UNITS OF
FURN.

NEW U/LAY
EXIST BAR +
GRIPPER



UPWT NEW
2x UNITS OF FURN

NEW U/LAY

EXISTING GRIPPER
+ D/BAR.