



S29245 HOXBY

BOTH ROOMS =
 UPPER NEED ON
 BOTH
 EXISTING + POTENTIALLY
 KNIPPER NEED FOR
 COVER BANKING &
 NEW DINING?



ASSUME SAME
 STRUCTURE AS
 MAIN WORK
 ROOM



UP TO STAIRS
 POTENTIAL

FOR
 WORKS
 UP
 ONE
 TO
 ACCURACY
 ISSUES

CURRENT FLOORING & SUB IS ACCURATE
 SOME AREAS HAVE HARD SUBFLOORS BUILT
 ON TOP OF CRT + ACCURATE, SO FLOOR
 GRIPPER ANCHORS WILL BE TRICKY,
 BECAUSE WE HAVE TO BE NERVOUS
 + STIPS OF PLY W/ STAIRS AS WE WANT FOR
 KNIPPER TO ACCURATE AS ITS TOO SOFT
 + WILL CAUSE A WEIGHT ISSUE

CONCEPT FOR THE STAIRS
 TO BE BUILT
 WITH
 GOOD STAIRS