

S29338

Friday, 12 January 2018

Prepared For Mehta

6 Issues Identified



Issue 1

Stairs like this need to be bolstered to tuck the carpet neatly against the skirting



Issue 2

Because the bit against the wall is one rib too wide, it is causing the edge of the stair carpet to pucker up. Can this be improved.



Issue 3

Customer is going to fix the facing of the cupboard here. The pressure from the bolster has pushed it back and the carpet has lifted off the gripper because of this. Please restretch back onto the gripper



Issue 4

In several areas in the property, the carpet needs restretching onto the gripper as it appears short in places. Please run through whole job



Issue 5

What happened here? I assumed the shadow created was because you followed the rib and the walls ran out but you can visibly see it's a rib short? Can this be improved at all?



Issue 6

PLEASE INSPECT ENTIRITY OF JOB!!!!
