

S31594
fisher

THESE AREAS NEED ATTENDING
TO AS THE PREP YOU HAVE
DONE IS SHOWING THROUGH
THE TILES NOW THAT THEY
ARE TIPPED.

I HAVE TOLD THE CUSTOMER
THAT THE WORK YOU DO WILL
IMPROVE THE FINISH BUT NOT
RESOLVE THE INHERENT ISSUES
ELSEWHERE.

