

S32019 - MORNICHE

- LARGE FRONT BEDROOM REQUIRES A RE-STRETCH

- AREAS OF THE RUNNER INSTALLED HAVE GRIPPER POKING OUT SIDE.

JOHN CRESSWELL DISCUSSED TRIMMING

GRIPPER BACK + POSSIBLY PUTTING A PIN IN IF IT WON'T LOOK TOO

BAD

- RE-STRETCH TO SMALL MAIN LAND THAT LEADS TO LOFT STAIRS + MASTER BEDROOM