

S35138 Diviney

Thursday 12th December 2024

1. Add patch of underlay at junction with Kitchen Floor (piece of underlay is missing here!)
2. Move doorbar to En-Suite so it will all sit beneath the pocket door as it is currently at an angle (customer has been advised that the door will likely need trimming)
3. Gripper in Rear Sitting Room needs moving closer to skirting, re-locate this & re-secure carpet as necessary
4. Use self-levelling compound (supplied previously) to smooth Top Landing, you had laid a patch of hardboard on a previous visit but this not appropriate as it has a harsh edge
5. Re-stretch all areas as customer reports majority has loosened up
6. Fit spare carpet (on site) to under stair cupboard WITH underlay
7. Ensure site is clean & tidy before leaving