

~~TOP~~

5 K.P.

Job No: F30577

Name:

Address:

TOP

Tip: 927

1 = 960

2 = 959

3 = 958

4 = 957

5 = 958

6 = 958

7 = 925

M/L = 919

1 = 960

2 = 953

3 = 955

4 = 955

5 = 955

6 = 956

7 = 938

2nd

Cam: 926

1 = 957

2 = 956

3 = 954

4 = 955

5 = 954

6 = 961

7 = 928

M/L = 927

1 = 956

2 = 958

3 = 958

4 = 964

5 = 956

6 = 961

7 = 925

1st

Sheet: 926

1 = 962

2 = ~~963~~ 961

3 = ~~963~~ 957

4 = ~~955~~ 956

5 = 959 956

6 = 957 956

7 = 957

8 = ~~962~~ 957

9 = 956

10 = 956

11 = 955

12 = 956

13 = 955

14 = 918

W/DN = 1481



ALL  
OPEN

BANNING

Curves  
Requires  
TEMPERATURE