

R15447 SANDLER SAT 20<sup>TH</sup> SEPT (FRIDAY LOADING).  
5 SOUTHSIDE COMMON  
WIMBLEDON  
SW19

8946 1179

LANDING

Fold back carpet in the landing corridor and reposition underlay. Replace 2 door bars as necessary. Refit carpet and insert new section on site to replace damaged seam. There is just sufficient to do this but it is tight.

