



The license associated with the Belarc Advisor product allows for **free personal use only**. Use on computers in a corporate, educational, military or government installation is prohibited. See the [license agreement](#) for details. The information on this page was created locally on your computer by the Belarc Advisor. Your computer profile was not sent to a web server. [Click here for more info.](#)

[About Belarc](#)

[System Management Products](#)

new
[Security Advisor for Android](#)

[Your Privacy](#)

In page Links:

[Software Licenses](#)

[Software Versions & Usage](#)

new
[Missing Updates](#)

[USB Storage Use](#)

[Hosted Virtual Machines](#)

[Network Map](#)

[Installed Hotfixes](#)

System Security Status

[Security Benchmark Score](#)
 0.63 of 10

[Virus Protection](#)
 Up-to-date

[Security Updates](#)
 23 missing (or more)†

† Advisor security definitions are out of date. [Click here](#) for the latest definitions.

Computer Profile Summary

Computer Name: MRCHOST121 (in MRCARPET2014) — New Image for VMware
Profile Date: 07 July 2015 13:34:39
Advisor Version: 8.4
Windows Logon: itsupport
DNS Suffix: mrcarpet2014.local

new [Click to try Belarc's Security Advisor for Android](#)

	Operating System	System Model
	Windows 7 Professional (x64) Service Pack 1 (build 7601) Install Language: English (United States) System Locale: English (United Kingdom) Installed: 01/06/2015 18:32:28 Boot Mode: UEFI (Secure Boot likely not supported by this UEFI)	VMware, Inc. VMware7,1 System Serial Number: VMware-42 39 0e 1a 70 b7 67 85-43 79 31 b4 65 5a 44 55 Enclosure Type: Other
	Processor ^a	Main Circuit Board ^b
	3.10 gigahertz AMD Opteron No memory cache 64-bit ready Multi-core (2 total) Not hyper-threaded	Board: Intel Corporation 440BX Desktop Reference Platform UEFI: VMware, Inc. VMW71.00V.0.B64.1404140612 04/14/2014
	Drives	Memory Modules ^{c,d}
	132.78 Gigabytes Usable Hard Drive Capacity 100.83 Gigabytes Hard Drive Free Space NECVMWar VMware SATA CD00 ATA Device [Optical drive] VMware Virtual disk SCSI Disk Device (132.88 GB) -- drive 0	3992 Megabytes Usable Installed Memory Slot 'RAM slot #0' has 2048 MB (serial number 00000001) Slot 'RAM slot #1' has 1024 MB (serial number 00000002) Slot 'RAM slot #2' has 512 MB (serial number 00000003) Slot 'RAM slot #3' has 256 MB (serial number 00000004) Slot 'RAM slot #4' has 128 MB (serial number 00000005) Slot 'RAM slot #5' has 16 MB (serial

number 00000006)
 Slot 'RAM slot #6' has 8 MB (serial number 00000007)
 Slot 'RAM slot #7' is Empty
 Slot 'RAM slot #8' is Empty
 Slot 'RAM slot #9' is Empty
 Slot 'RAM slot #10' is Empty
 Slot 'RAM slot #11' is Empty
 Slot 'RAM slot #12' is Empty
 Slot 'RAM slot #13' is Empty
 Slot 'RAM slot #14' is Empty
 Slot 'RAM slot #15' is Empty
 Slot 'RAM slot #16' is Empty
 Slot 'RAM slot #17' is Empty
 Slot 'RAM slot #18' is Empty
 Slot 'RAM slot #19' is Empty
 Slot 'RAM slot #20' is Empty
 Slot 'RAM slot #21' is Empty
 Slot 'RAM slot #22' is Empty
 Slot 'RAM slot #23' is Empty
 Slot 'RAM slot #24' is Empty
 Slot 'RAM slot #25' is Empty
 Slot 'RAM slot #26' is Empty
 Slot 'RAM slot #27' is Empty
 Slot 'RAM slot #28' is Empty
 Slot 'RAM slot #29' is Empty
 Slot 'RAM slot #30' is Empty
 Slot 'RAM slot #31' is Empty
 Slot 'RAM slot #32' is Empty

Local Drive Volumes

c: (NTFS on drive 132.78 100.83 0) GB GB free

Network Drives

mounted by itsupport at 07/07/2015 13:29:26

i: \\192.168.13.64 5986.305562.68 GB GB free
 \mrcdb
 r: \\192.168.13.64 5986.305562.68 GB GB free
 \measures_ho
 s: \\192.168.13.64 5986.305562.68 GB GB free
 \allwork_ho
 t: \\192.168.13.64 5986.305562.68 GB GB free
 \sun4_ho
 v: \\192.168.13.64 5986.305562.68 GB GB free
 \cuttingplans_ho

Users (mouse over user name for details)

local user accounts	last logon
Administrator	01/06/2015 21:32:30(admin)
jdc	11/07/2014 14:28:39(admin)
local system accounts	
___VMware_Conv_SA___	never
✘ Guest	never

Printers

Microsoft Shared Fax Driver	on SHRFX:
Microsoft XPS Document Writer	on XPSPort:
pdfFactory 4	on FPP4:

microcare	05/02/2015 12:15:16(admin)
MRCARPET2014 domain logons	
ANDY	10/02/2015 23:05:32
davidg	24/06/2015 22:58:34
itsupport	07/07/2015 13:23:46(admin)
JOHNMC	18/06/2015 13:54:05

✘ Marks a disabled account; 🔒 Marks a locked account

Controllers

Standard floppy disk controller
 ATA Channel 0 [Controller] (2x)
 ATA Channel 1 [Controller] (2x)
 ATA Channel 10 [Controller]
 ATA Channel 11 [Controller]
 ATA Channel 12 [Controller]
 ATA Channel 13 [Controller]
 ATA Channel 14 [Controller]
 ATA Channel 15 [Controller]
 ATA Channel 16 [Controller]
 ATA Channel 17 [Controller]
 ATA Channel 18 [Controller]
 ATA Channel 19 [Controller]
 ATA Channel 2 [Controller]
 ATA Channel 20 [Controller]
 ATA Channel 21 [Controller]
 ATA Channel 22 [Controller]
 ATA Channel 23 [Controller]
 ATA Channel 24 [Controller]
 ATA Channel 25 [Controller]
 ATA Channel 26 [Controller]
 ATA Channel 27 [Controller]
 ATA Channel 28 [Controller]
 ATA Channel 29 [Controller]
 ATA Channel 3 [Controller]
 ATA Channel 4 [Controller]
 ATA Channel 5 [Controller]
 ATA Channel 6 [Controller]
 ATA Channel 7 [Controller]
 ATA Channel 8 [Controller]
 ATA Channel 9 [Controller]
 Intel(R) 82371AB/EB PCI Bus Master IDE Controller
 Standard AHCI 1.0 Serial ATA Controller

Bus Adapters

LSI Adapter, SAS 3000 series, 8-port with 1068
 Standard Enhanced PCI to USB Host Controller
 Standard Universal PCI to USB Host Controller

Virus Protection [\[Back to Top\]](#)

OfficeScan Corporate Edition Version 19.0
 Virus Definitions Version 07/07/2015 Rev 1.000.00
 (000)
 Realtime File Scanning On
Trend Micro Security Agent

Communications

↑ Intel(R) PRO/1000 MT Network Connection
 primary Auto IP Address: 192.168.13.25 / 24
 Gateway: 192.168.13.254

Display

PCI GDIHOOK5 [Display adapter]
 VMware SVGA 3D [Display adapter]
 Generic Non-PnP Monitor

Multimedia

VMware Virtual Audio (DevTap)
 VMware Virtual Microphone

Group Policies

None discovered

Other Devices

Microsoft AC Adapter
 Microsoft Composite Battery
 USB Input Device (2x)

Dhcp Server:	192.168.13.254	VMware Virtual Webcam
Physical Address:	00:50:56:B9:59:74	VMware Virtual WIA Scanner
Connection Speed:	1 Gbps	Standard PS/2 Keyboard
Microsoft ISATAP Adapter		VMware Pointing Device [Mouse]
Teredo Tunneling Pseudo-Interface		VMware USB Pointing Device [Mouse]
		(2x)
Networking Dns Server:	192.168.0.1	Generic USB Hub
		USB Composite Device
		USB Root Hub (2x)
		VMware View Virtual USB Host
		Controller
		VMware View Virtual USB Hub
		Generic volume shadow copy
USB Storage Use in past 30 Days (mouse over last used for details)		Hosted Virtual Machines (mouse over name for details)
<i>None discovered</i>		<i>None discovered</i>

[See your entire network map...](#)
[click for Belarc's System Management products](#)

Network Map (mouse over IP address for physical address) [[Back to Top](#)]

No details available

[Find your security vulnerabilities...](#)
[click for Belarc's System Management products](#)

Missing Security Updates **new** – for Adobe, Apple, Java, Microsoft and more [[Back to Top](#)]

Hotfixes from Windows Update (agent version 7.6.7601.18804) .

These security updates apply to this computer but are not currently installed (using Advisor definitions version 2013.12.13.1), according to the 12/10/2013 Microsoft Security Bulletin Summary and bulletins from other vendors. Note: Security benchmarks require that *Critical* and *Important* severity security updates **must be installed**.

Hotfix Id **Severity** **Description (click to see security bulletin)**

EOL-Adobe	End of Life	Adobe Reader 9.5.0.270 is vulnerable and no security updates are provided by the vendor
Q2538243	Important	Microsoft security update (KB2538243)
Q2584146	Important	Microsoft security update (KB2584146)
Q2685939	Critical	Microsoft security update (KB2685939)
Q2743555	Important	Microsoft security update (KB2743555)
Q2756921	Important	Microsoft security update (KB2756921)
Q2757638	Critical	Microsoft security update (KB2757638)
Q2833946	Critical	Microsoft security update (KB2833946)
Q2834886	Critical	Microsoft security update (KB2834886)
Q2835364	Critical	Microsoft security update (KB2835364)
Q2840149	Moderate	Microsoft security update (KB2840149)
Q2844286	Important	Microsoft security update (KB2844286)
Q2845187	Critical	Microsoft security update (KB2845187)
Q2849470	Important	Microsoft security update (KB2849470)
Q2861855	Unrated	Microsoft security advisory (KB2861855)
Q2862330	Important	Microsoft security update (KB2862330)
Q2863240	Important	Microsoft security update (KB2863240)

Q2868725	Unrated	Microsoft security advisory (KB2868725)
Q2875783	Important	Microsoft security update (KB2875783)
Q2876284	Important	Microsoft security update (KB2876284)
Q2876331	Critical	Microsoft security update (KB2876331)
Q2893984	Important	Microsoft security update (KB2893984)
Q2917500	Unrated	Microsoft security advisory (KB2917500)

[Manage all your software licenses...](#)
[click for Belarc's System Management products](#)

Software Licenses [\[Back to Top\]](#)

Belarc - Advisor	6a4e1910
Microsoft - Internet Explorer	00371-OEM-9046531-17084 (Key: none activated) ^e
Microsoft - Office Basic Edition 2003	73102-OEM-5695566-02556 (Key: B9XY9-C2QD6-FV93T-J728C-V9PT8) ^e
Microsoft - PowerShell	89383-100-0001260-04309
Microsoft - Windows 7 Professional (x64)	00371-OEM-9046531-17084 (Key: none activated) ^e

[Find unused software and reduce licensing costs...](#)
[click for Belarc's System Management products](#)

Software Versions & Usage (mouse over **i** for details, click **i** for location) [\[Back to Top\]](#)

i Adobe Systems - Acrobat Version 9.5.0.270	i Microsoft - Windows Media Player Version 12.0.7600.16385 (32/64-bit)
i Adobe Systems - Reader and Acrobat Manager Version 1.5.7.0	i Microsoft - Windows Script Host Version 5.8.7600.16385 (32/64-bit)
i Adobe Systems - Reader Version 9.5.0.270	i Microsoft - Windows Search Version 7.00.7600.16385 (32/64-bit)
i Adobe Systems - Shockwave Flash Version 14,0,0,145 (32/64-bit)	i NetSupport - Manager V10.02
i Belarc - Advisor Version 8.4	ii NetSupport - Manager V12.01
i Cortado - ThinPrint Virtual Channel Gateway Version 10,2,266,2 (64-bit)	i No Company Name - Device Redirection Common Version 3.0.13.0 (64-bit)
i Cortado - TPAutoConnect Version 10,2,561,2 (64-bit)	iii i No Company Name - I from ANGOSS
i FinePrint Software - pdfFactory Version 4.75 (64-bit)	i No Company Name - Scanner Redirection Version 1.0.22.0
ii i Google - Chrome Version 43.0.2357.130	i No Company Name - ScanToPDF Version 4.2.0.20
i Google - Update Version 1.3.26.9	i No Company Name - Win32 API Viewer
i Microsoft - .NET Framework Version 2.0.50727.5483 (32/64-bit)	i Piriform - CCleaner Version 4, 15, 00, 4725 (32/64-bit)
i Microsoft - .NET Framework Version 3.0.6920.5011 (64-bit)	i Trend Micro - AEGIS Version 2.97 (64-bit)
i Microsoft - .NET Framework Version 4.0.41210.0 (32/64-bit)	i Trend Micro - Common Client Version 19.00 (64-bit)
i Microsoft - Application Error Reporting Version 11.0.5515	i Trend Micro - Network Security Components Version 5.82 (64-bit)
i Microsoft - Clip Organizer Version 11.0.5510	i VMware - Blast Desktop Server Version 2.1.0-2316948 (64-bit)
i Microsoft - Internet Explorer Version 11.00.9600.17801 (32/64-bit)	i VMware - Serial Com Redirection Agent Version 1.0.16.0
iii i Microsoft - Office 2003 Version 11.0.5612	i VMware - Serial COM Redirection for VMware Horizon Version 1.0.16.0
i Microsoft - Office Document Imaging Version 11.0.1897.0	i VMware - Tools Version 9.4.10 build-2068191 (64-bit)
i Microsoft - Office InfoPath Version	

11.0.5510 i Microsoft - Office Outlook Version	i VMware - vCenter Operations Manager for Horizon Version 6.0.0.2041012 (64-bit)
11.0.5510 i Microsoft - Office Picture Manager Version	i VMware - View Composer Version 6.0.1 build-2078421
11.0.5510 i Microsoft - Office Save My Settings/Profile Wizard Version 11.0.5510	i VMware - View Persona Management Version 6.0 (64-bit)
11.0.5525 i Microsoft - Office Source Engine Version	i VMware - View Version 6.0.1 build-2088845 (64-bit)
iii Microsoft - Windows Installer - Unicode Version 5.0.7600.16385 (32/64-bit)	i VMware - Workstation Version 11.0.0 build-2316728
	iii Zedtek - ZTreeWin Version 2.4.121 (64-bit)

- [i](#) Mouse over to see details, click to see where software is installed.
- [i](#) Marks software last used within the past 7 days.
- [ii](#) Marks software last used within the past 90 days, but over 7 days ago.
- [iii](#) Marks software last used within the past year, but over 90 days ago.
- [iiii](#) Marks software last used over 1 year ago.
- Unmarked software lacks the data to determine last use.

[**Audit your security posture...
click for Belarc's System Management products**](#)

Installed Microsoft Hotfixes [\[Back to Top\]](#)

[Click here to see all installed hotfixes.](#)

- a. Processor clock speed is measured at computer start-up, and on laptops may be impacted by power option settings.
- b. Data may be transferred on the bus at one, two, or four times the Bus Clock rate.
- c. Memory slot contents may not add up to Installed Memory if some memory is not recognized by Windows.
- d. Memory slot contents is reported by the motherboard BIOS. Contact system vendor if slot contents are wrong.
- e. This may be the manufacturer's factory installed product key rather than yours. You can change it to your product key using the procedure at <http://www.belarc.com/msproductkeys.html>.
- f. The full product key is not stored on this computer. However, the characters shown uniquely identify your product key.
- g. You can have Windows save the full product key using the procedure at <http://www.belarc.com/msproductkeys.html>.

Copyright 2000-13, Belarc, Inc. All rights reserved.

[Legal notice](#). U.S. Patents 5665951, 6085229 and Patents pending.
