

SEE PHOTO

Heated towel rail pipe is made of plastic and very close to the floorboards (Poor install)

As soon as you step on the section of floor, the plastic pops out and water leaks

Plumber is round to resolve the issue and make it safe for install, we will return at a later date

