

F25216 Taylor

30 Mablethorpe Road SW6 6AH

Saturday, 24 September 2016

Prepared For Alex Taylor

Identified 3 Issues

Colin Symonds

Mr Carpet Ltd



Issue 1

To obtain a superior finish the 5th step up on the 1st flight of stairs would need repair by the appropriate tradesman prior to carpet installation



Issue 2

A wooden nosing should be installed by your carpenter / builder at the top step of the first flight of stairs (as shown with red arrows on photograph) as we would be finishing the carpet at the top of the last riser (as shown with white arrows on photograph)



Issue 3

12mm easy shim required if tile edge doorbar is used at small bedroom doorway connection to wood floor on the 1st floor landing. It will also be the same scenario with the carpet in the loft bedroom where the carpet meets en suite bathroom tiles.
