

P27208

1 Rosedale Road SW15 1AD

Thursday, 11 August 2016

Prepared For Joanna Shaw

Identified 3 Issues



Colin Symonds

Mr Carpet Ltd



Issue 1

Riser at top of first flight of stairs will need to have scotia beading removed by builder to facilitate installation of a taped stair runner and then the sides of riser should be painted accordingly



Issue 2

The First flight of stairs and top riser will require both sides of each tread & risers to be painted an adequate width to accommodate the proposed stair runner. The carpet runner width will require some discussion and confirmation with our sales persons at our Putney showroom before final pricing



Issue 3

The Stair runner will need to be shaped on the bottom bullnose steps. As briefly discussed / advised on site, it may look aesthetically more pleasing if only the tread is fitted as a runner and then the bottom riser is painted?
