

# R17378 Middleton

38 Ernle Road SW20 0HL

Monday, 19 September 2016

## **Identified 1 Issue**

Colin Symonds

Mr Carpet Ltd



### **Issue 1**

Top riser of the first flight of stairs will require scotia beading to be removed by others to facilitate installation of the new stripe carpet on the riser and then to relay existing landing carpet (plain) over the lip of the landing to meet the striped carpet on the riser

---