

P27182 - Collen

Fitting instructions


Monday, 1 August 2016

Prepared For Mrs Collen

Identified 2 Issues

Nigel Symonds

Mr Carpet Ltd



Master bed / Dressing Room Junction

Builder to remove T/Hold & vinyl in dressing room side & make good floor if necessary. Seam new carpet across this opening



Bullnose Step

Fit carpet around this obstruction as existing. Carpet is being laid as a temporary measure for a couple of years before the house undergoes a major refurbishment