


Keys from HDWE

mrcarpet  
Job No: P27673  
Name: HDWE  
Address: 7a Devershire Place  
Tel:  
Sheet: of 1 of 2



Silk Touch  
Col. SLK-335

$$425 \times 500 = \underline{\underline{2125m^2}}$$

*Ply floor*

EX CARPET stuck to Cloud 9 Contract u/Lay  
which is tackified to the existing ply sub-floor  
Needs new s/e All round

\* Above example only  
Hoover on Completion.

P27673  
HDWE  
2012



**PHOTO 1**

The existing carpet is stuck to the underlay & the underlay is stuck to the floor



**PHOTO 2**

The existing carpet is stuck to the underlay & the underlay is stuck to the floor