

Lounge

Wrong alloy fitted.

Need to change to
Low Tog.

Also: Bathroom, fitted last year.

2 small bubbles need flattening

(10/1)

R17627

MRS J STITT

No 33 Lambton Road

Address:

SW20 0LW

Sheet:

of:

Kenns Grad.

17/4/18

1st call