


Customer not happy with  
turn + tack at bannisters

Pull back the carpet carefully

Improve on the tack marks in  
the carpet

Put straps, mitred, as shown



Landing

(1001)

R17901

Mrs V. FRANKE  
21 Raymond Road  
Wimbledon  
SW19 4AD

Tel: ..... of: .....