

PROJECT 18/06/2018, 11:44

Monday, 18 June 2018

Prepared For S29912 Bullworthy

3 Issues Identified



ISSUE 1

Cut back underlay on step so not visible.



ISSUE 2

Cut back gripper on Winder 6 as it finishes flush with carpet at present



ISSUE 3

Tighten up Winder 3 as loose on riser