

S31114

SHAH

Riser 0204082

(13)

02804082



wood

Risers are  
weak mdr

needs stida

plenty spray

no ulo

FOR U1

30/7/19

12/ Date

(1)

1.00	1.00	1.00	1.00
Riser	(4)	(4)	(2) 2.00
+			
(3) 4.00			
			SPACE LEAVE WITH CUSTOMER

FOR (1) 4.00 x 4.00