


(FRONT)



S32639  
Phillips  
1 OF 1.

Rutland 50  
Col. RUT50N29

$$= 7.25 \times 4.00$$
$$= \underline{\underline{29M^2}}$$

THE MANUFACTURE IS  
SENDING 5M WIDE

Damaged OAK T/Hold (50mm Wide)  
Change to Solid BRASS S/NAP

u/d - Wool Twist on Rubber

Re-use ex s/e

M/F x 5 (Customer advised to empty units)

move upright Piano into Conservatory but protect  
Wood flooring with H/BOARD First!