


W12 8 71
LIAM MAY
33 + 334 Felsham Rd.
Putney
SW15 1AY.



Raised Pipes.

- ① Ply Entire Area. Cutting around pipes. Fit 2nd Layer of Ply over pipes up to Edge of wall. Feather ply off into Room.
- ② Fit up to raised Plyths under all Machines + to Threshold + Under Stairs etc.
- ③ Fit tiles into meter Cupboard by front door.

IMPORTANT
Collect keys day 1
Bruce May
16 Dove Park Drive
London
SW15 SBC.
Post through letter box
when complete.