


Job No: F29714

Name:

Address:


Tel:

Sheet: 1/1



NO VLD  
 NO FLN  
 EX DIN  
 NEW SIE  
 NEW ULAY  
 NEW CRT

35x400



- CERAMIC TILES DOWN.
- ASSUMPTION IS THAT TILES ARE GLUED TO A PLYWOOD SUBFLOOR.
- WILL AU NEED TAKING UP + FURTHER INSPECTION