

NIEBUKE



mrcarpet
DESIGNS FOR FLOORS

Job No: F30378


Name: CAROLINE

Address: VAN MEGHTELEN

TIAT 5

Tel: 55 DEAYTON

Sheet: SW10 9EM



F30378

2nd call of 5

Notes for Measure

Estimator: MannyD

Caroline Van Meghelen, Flat 5

Date of Measure: Tue, 18 Mar 25

At: 10.00am - 11.00am

Site Address:

Flat 5
55 Drayton Gardens

LONDON SW10 9RU

CONTACT: As customer details

Mobile	Home	Office
07793-488356		

Customer Address:

Flat 5
55 Drayton Gardens
LONDON

Zamita
SW10 9RU

Email:
carolinevm@gmail.com

Areas to be done and Description of Measure

Measure living room that has been shrunk by cleaners

F28057

Bt Pavei
col 112
Stone

39.50
6m

Instructions and Estimators comments

Match up to existing material - PLEASE TAKE PHOTO OF CARPET/SISAL

Must Read!

Call Saskia 07863-069626 (BUZZER NOT WORKING)

Office Ref: F30378

Caroline Van Meghelen, Flat 5

Date of Measure Tue, 18 Mar 25

At 10.00am - 11.00am

Door: Wood / Concrete / other _____

S/edge: Wood/Concrete/No pin/existing (if existing, allow ___ sticks to supplement where necessary)

Sticking Req'd: Yes/No Type: Fastset/Other

Underlay: Re-use Existing / New required

Type: 42oz Felt / Fomalux / PU Foam / Luxury PU Foam / LowTog / Durafit NO

Doorbars: Alloy / Satin Ali / Polished Ali / Anod / Solid Brass / Chrome / Nisheen
Seam/Wood/T/Holds: colour _____

Door Clearance: OK / Low (advise on quote)

Uplift: No / Yes (if "Yes" - what type?) _____

Furniture: No/Yes (if YES, please specify the following) - 1 man / 2 men (Fitter to get paid) £_____ total/per room Bad Start

Parking Cost: Free / £ 7 per hour

Parking Restrictions: (type) / £ _____ Permit All Round

Congestion Zone: No / Yes

Access: Easy / Hard / 2 men req'd / 5 floor? 1st Floor Lift not Working

Runners: Whipping / Binding (if binding, specify type)

Tape size: 1½" / 2" / 3" / 5"

Style: Top taping / Side binding

Stairrods: Type _____ Nr _____ Size _____

Must Read: Call Saskia 07863-069626 (BUZZER NOT WORKING)