


1st flr

BOULDER
SOLIN

Job No: F30655
Name: ASHTON
Address: 63 FILMER RD
SW6 7JF
Tel: _____
Sheet: _____ of: _____

19mm
GAP



Area: 1st flr Bed
Floor: Wood / Conc /
S/Edge: Existing / Reqd / NA
U/lay: Existing / Reqd / NA
Uplift: Yes / No / NA
Furn: Yes / No / NA
Door: OK / Needs Cut / NA
UFH: Yes / No / NA
D/bars: Existing / Reqd / NA
Notes: TBC

Area: _____
Floor: Wood / Conc /
S/Edge: Existing / Reqd / NA
U/lay: Existing / Reqd / NA
Uplift: Yes / No / NA
Furn: Yes / No / NA
Door: OK / Needs Cut / NA
UFH: Yes / No / NA
D/bars: Existing / Reqd / NA
Notes: _____

Area: _____
Floor: Wood / Conc /
S/Edge: Existing / Reqd / NA
U/lay: Existing / Reqd / NA
Uplift: Yes / No / NA
Furn: Yes / No / NA
Door: OK / Needs Cut / NA
UFH: Yes / No / NA
D/bars: Existing / Reqd / NA
Notes: _____

Area: _____
Floor: Wood / Conc /
S/Edge: Existing / Reqd / NA
U/lay: Existing / Reqd / NA
Uplift: Yes / No / NA
Furn: Yes / No / NA
Door: OK / Needs Cut / NA
UFH: Yes / No / NA
D/bars: Existing / Reqd / NA
Notes: _____


- * N9 0.94 x 0.63 o/r
- W10 1.09 x 0.69 o/r
- W11 0.75 x 0.61 o/r
- 11 @ 0.79 + T/T x 0.44 o/r
- B/N 0.90 x 0.40 o/r

FRONT OF HOUSE

DIN | SIN | Z/B
1 | 1 | 1

Job No: F30655
 Name: ASHTON
 Address: 63 FILMER RD
 SW6 7JF
 Tel: _____
 Sheet: _____ of: _____

TOP floor



Area: TOP BED
 Floor: Wood / ~~Conc~~ /
 S/Edge: Existing / Req / NA
 U/lay: Existing / Req / NA
 Uplift: Yes / No / NA
 Furn: Yes / No / NA
 Door: OK / Needs Cut / NA
 UFH: Yes / No / NA
 D/bars: Existing / Req / NA
 Notes:

- W1 0.84 x 0.57 OR
 - W2 1.07 x 0.58 OR
 - W3 1.07 x 0.74 OR
 - W4 0.78 x 0.58 OR
 - W5 0.83 x 0.56 OR
 - W6 1.09 x 0.58 OR
 - W7 1.10 x 0.72 OR
 - W8 0.77 x 0.57 OR
- Area:
 Floor: Wood / Conc /
 S/Edge: Existing / Req / NA
 U/lay: Existing / Req / NA
 Uplift: Yes / No / NA
 Furn: Yes / No / NA
 Door: OK / Needs Cut / NA
 UFH: Yes / No / NA
 D/bars: Existing / Req / NA
 Notes:
- LAND (B)


DIN	SIN	2/B
1		1

FRONT OF HOUSE

Area: STAIRS
 Floor: Wood / ~~Conc~~ /
 S/Edge: Existing / Req / NA
 U/lay: Existing / Req / NA
 Uplift: Yes / No / NA
 Furn: Yes / No / NA
 Door: OK / Needs Cut / NA
 UFH: Yes / No / NA
 D/bars: Existing / Req / NA
 Notes:

BASEMENT

Job No: F30655
 Name: ASHTON
 Address: 63 Finnerley
 SW6 7JF
 Tel: _____
 Sheet: _____ of: _____



Area: BASEMENT 60
 Floor: ~~Wood~~ / Conc / _____
 S/Edge: Existing / Reqd / NA
 U/lay: Existing / Reqd / NA
 Uplift: Yes / No / NA
 Furn: Yes / No / NA
 Door: OK / Needs Cut / NA BSS
 UFH: ~~Yes~~ / No / NA
 D/bars: Existing / Reqd / NA
 Notes: _____

Area: _____
 Floor: Wood / Conc / _____
 S/Edge: Existing / Reqd / NA
 U/lay: Existing / Reqd / NA
 Uplift: Yes / No / NA
 Furn: Yes / No / NA
 Door: OK / Needs Cut / NA
 UFH: Yes / No / NA
 D/bars: Existing / Reqd / NA
 Notes: _____

Area: _____
 Floor: Wood / Conc / _____
 S/Edge: Existing / Reqd / NA
 U/lay: Existing / Reqd / NA
 Uplift: Yes / No / NA
 Furn: Yes / No / NA
 Door: OK / Needs Cut / NA
 UFH: Yes / No / NA
 D/bars: Existing / Reqd / NA
 Notes: _____

Area: _____
 Floor: Wood / Conc / _____
 S/Edge: Existing / Reqd / NA
 U/lay: Existing / Reqd / NA
 Uplift: Yes / No / NA
 Furn: Yes / No / NA
 Door: OK / Needs Cut / NA
 UFH: Yes / No / NA
 D/bars: Existing / Reqd / NA
 Notes: _____

FRONT OF HOUSE

MIGHT NEED S/N IF FLOOR RAISED TO REDUCE GAP UNDER SKIRTINGS

