


GROUND FLOOR

Job No: P26274  
Name: LLOYD  
Address: .....  
Tel: .....  
Sheet: ..... of: .....



BUILDERS UNSURE WHERE  
SITTING ROOM ENDS AND  
KITCHEN BEGINS!

**MUST CHECK!** BUILDING NOT COMPLETED.  
EXISTING UNDERLAY IS IN POOR CONDITION AND  
COVERED IN RUBBLE. SMOOTHEDGE IS MISSING IN  
LOOPS OR AREAS.