

WARRANTY CALL

ATTEND TO RUNNERS

S26310

Mrs Kelson
16 SHIRLEY ROAD
Crawley
Wt 1DD

Bottom 3 runners need looking at.

- ① End of tape showing on tread, needs stretching onto sledge
- ② R.H side flapping, needs tack

Landing where fitted to under nosing. gap at far end.
Customer can get her bungs in it, and want it sorted.

Ms Kelson will go over it with you

1 of 1

D. Gladwyn
Mon 10/2/14 (8:15-4)
(around lunchtime)