

Rebecca Wynne
Showroom Installation Co ordinator
Tel 01386 820159 Fax 01386 820178
Karndean International
Bramley Drive
Vale Park
Evesham, WR11 1JH



Company Name MR CARPET LTD Acc No. MRC123
Date of Installation 1st NOV 12

In an attempt to keep the standard of our service as high as possible we would be grateful if you could answer the questions below following the installation of your Showroom.

Please tick if the following items have all been installed to your satisfaction:

Swing Arm Units	<input checked="" type="checkbox"/>	Litrature Unit	<input checked="" type="checkbox"/>
Play Table	<input checked="" type="checkbox"/>	Bookend unit	<input checked="" type="checkbox"/>
Vangogh Midfloor Unit	<input checked="" type="checkbox"/>	PC & TV	<input checked="" type="checkbox"/>
Design Table	<input checked="" type="checkbox"/>		

Comments: * DESIGN TABLE HAS 2 SMALL CHIPS IN SURFACE AS SEEN BY MARK ROBINSON. ALSO LIGHT OVER TABLE HAS TAPE MARKS INSIDE. WE WILL TRY TO REMOVE THEM.

How successful do you consider the overall Showroom installation?

	Excellent (1)	Good (2)	Average (3)	Poor (4)	Very Poor (5)
Quality of Service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
What condition was Showroom Left in?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Installation Start Time?	<u>5:15am</u>				
Installation Finish Time?				<u>16:30</u>	

Any Comments? STAFF WERE VERY HELPFUL + POLITE. THEY HAD AN ~~ISSUE~~ PROBLEM WITH 1 UNIT THAT THEY RESOLVED BEFORE I WAS REALY AWARE.

Signed [Signature]
Print Name D. CUYAN
Position in Company DIRECTOR
Area Representative Signed _____
Date _____

I confirm that the Showroom is completely to my satisfaction and payment is now due in accordance with contract.
WITH THE PROVISIO THAT IF WE CANNOT FIX / REMOVE THE TAPE MARKS TO LIGHT BOX + DESK TOPS TABLE TOP CHIPS ARE INVESTIGATED FURTHER