

P27558 - Shuber

Thursday, 2 March 2017

Identified 11 Issues

Jack Barton

Mr Carpet Ltd





Front Door Threshold

Low in centre.

Approx 2-3mm high at sides.



Front Door Threshold

Low in centre.

Approx 2-3mm high at sides.



Front Door Threshold

Low in centre.

Approx 2-3mm high at sides.



Front Door Area

Door is low, approx 3mm clearance at far end, customer advised will need to be trimmed.

- Advise customer of how much to trim off.



WC Door Threshold

Low threshold - Approx 2 high

Low door - will need trimming (advise cust)



Cupboard Door Threshold

Fit up to existing wooden upstand

Low door - will need trimming (advise cust)



Cupboard Door Threshold

Fit up to existing wooden upstand

Low door - will need trimming (advise cust)



Front Window Recess

Recess to right hand side of front door (photo looking from rear to front).

Utility boxes in place, may only be able to fit up to, not underneath.

Loose skirting - see next aspect.



Front Window Recess Skirting

Gapped & slightly loose skirting - advise customer to secure in place.

Folded foam packing underneath is beneath ALL skirting around area.



Area Overview (from Front to Rear)



Existing Sub-floor

Icopal

Monarfloor Tri-Deck

35mm sheets direct over joist
