

Colin Symonds
Mr Carpet Ltd

P28156 FAWTHROP

25 Furmage Street SW18 4DF

Thursday, 1 February 2018

Prepared For Sam Fawthrop

2 Issues Identified



BROKEN WINDER STAIRS

Risers need repair by appropriate tradesman prior to installation of stair runner



SCOTIA BEADING REMOVAL

The scotia beading would need to be removed and the gap filled and decorated accordingly to facilitate installation of a stair runner