

# P28227 Burrows

Wednesday, 21 March 2018

**23 Issues Identified**

Jack Barton

Mr Carpet Ltd





### Issue 1

1st Floor Landing - cupboard (part t/h across opening)

---



### Issue 2

1st Bath - ex vinyl tiles uneven, raised toilet


---



### Issue 3

1st Bath - ex vinyl tiles uneven, raised toilet

---



### Issue 4

1st Floor Rear Bedroom - Iron unit in fire place

---



### **Issue 5**

1st Floor Rear Bedroom

---



### **Issue 6**

Ground Floor Bathroom - damp sub-floor beneath cushion vinyl

---



### **Issue 7**

Ground Floor Bathroom - damp sub-floor beneath cushion vinyl

---



### Issue 8

Ground Floor Bathroom

---



### Issue 9

Ground Floor Bathroom


---



### Issue 10

Ground Floor Bathroom

---



### Issue 11

Kitchen

---



### Issue 12

Kitchen

---



### Issue 13

Kitchen

---




**Issue 14**  
Kitchen

---



**Issue 15**  
Kitchen

---




**Issue 16**  
Kitchen (floor has dropped beneath F/F)

---



**Issue 17**  
Conservatory

---




**Issue 18**  
Conservatory

---



**Issue 19**  
Conservatory

---



**Issue 20**  
Conservatory

---



**Issue 21**  
Conservatory

---



**Issue 22**  
Conservatory

---



**Issue 23**  
Conservatory

---