





Job No: F24868  
 Name: LDB  
 Address: 613 FULHAM RD  
 FULHAM SW6 5UR  
 Tel:  
 Sheet: 1 of 2

STATESIDE GEORGIA



\* MOTH DAMAGE IN HALL  
 TOP LANDING 2 STAIRS

\* FITTER PLEASE NOTE \*  
 IF WE CAN USE PART OF  
 THE TOP LANDING THAT IS  
 NOT MOTH EATEN TO REMOVE  
 THE DINSE + 2 STAIRS  
 TO KEEP THE STAIRS CONSISTANT



120 X 170

Job No: F 24868  
 Name: LETS DO BUSINESS  
 Address: 613 FULHAM RD.  
 FULHAM  
 Tel: SW6 5UQ  
 Sheet: 2 of 2


STAIRS (6) - 43 X 78

1/2 LAND 105 X 70

1/2 LAND 103 X 80


STAIRS (7) - 43 X 80

B NOSE - 50 X 100




ST (6) - 45 X 80

1ST LAND  
 RISE - 30 X 80  
 1ST - 50 X 90



W 1 65 X 1.02  
 W 2 75 X 1.20  
 W 3 65 X 80



ST (7) - 45 X 78  
 DN NOSE - 50 X 100