

Conservatory (Remedial Work)

mrcarpet

P27284

Job No:

Name:


Milne

Address:

Tel:

T/Kange

2 of 5



* Patch in where tiles have been lifted. Screed in as best possible & fit tiles on site (17 No)

P27284

MILNE

3 of 5



Conservatory Remedial Work

Take and and up tiles back to nearest full planks, patch screed holes & fit patch in using customers spare tiles on site (17 planks on site)



Conservatory Remedial Work

Take and and up tiles back to nearest full planks, patch screed holes & fit patch in using customers spare tiles on site (17 planks on site)



Conservatory Remedial Work

Man hole cover to be changed, patch in using customers spare tiles on site (17 planks on site)

P27284
Milne
4 of 5



Conservatory Remedial Work

Take and and up tiles back to nearest full planks, patch screed holes & fit patch in using customers spare tiles on site (17 planks on site)



Hall Door

Fit new tiles to marry up with existing tiles in hall



Door Between T/Lounge & Conservatory

Fit one full plank across this opening to avoid having to join tiles end to end

P27284
Milne
5 of 5



Door Between T/Lounge & Conservatory

Fit one full plank across this opening to avoid having to join tiles end to end



Through Lounge

Customer to clear room prior to fitting



Through Lounge

Customer to clear room prior to fitting