


Faux Silk

Col. FAU027



$$= 335 \times 400$$
$$= 13.40m^2$$

EX Fitted W/Robe to be removed.

### \* MASTER BATH Doorway (Remedial)

Please have a look at the Carpet in the Master Bedroom where it meets the tiles in the Master Bathroom. I think the Builder removed the gripper to fit the sliding glass doors which is causing a dip in the carpet. Please either patch in the underlay & fix the carpet with spray adhesive or remove the skir & fit gripper up against the tiles so that the carpet looks better.