

Job No: P27554

Name: Hale


Address:

Tel:

Sheet:

1 of 1

Broken floorboard  
\* Builder to repair



Run CARPET into Fireplace

Conc  
Conc Hearth  
stick s/e

Run CARPET into Cup'd Doors have 25mm Clearance

D/W  
Replace D/W & fit in correct place.

1/4ay 19m<sup>2</sup>